

Name: Golf Course machinery wash down 'Oily Waste Separator'

Waste type: Oils, fuels and organics.

Problems:

1. Pungent Odour emanating from open pipe feeding to sewer main.
2. Filter requiring regular cleaning due to bio film build-up.

Solution:

1. Dose underground collection tank with For Earth pro-biotic bacteria products for organics and hydrocarbons.

Results:

1. Odour totally eliminated from system.
2. Very little bio film build-up on filter.
3. Less oil scum on separator surface for removal.



Machinery wash down pad



Collection tank, water pumped to separator.

